

**From:** [Wallingford, Jonni B.](#)  
**To:** [Sheldrake, Sean](#); [Zhen, Davis](#)  
**Cc:** [younghs@cdmsmith.com](mailto:younghs@cdmsmith.com); [Scott Coffey](#)  
**Subject:** Fish Acoustic Oversight  
**Date:** Wednesday, October 3, 2018 10:52:53 AM  
**Attachments:** [IMG\\_20181003\\_103240820\\_HDR.jpg](#)  
[IMG\\_20181003\\_103335830\\_HDR.jpg](#)

---

Hello,

The Pre-RD has just retrieved AR-A27 (RM 9). The receiver was attached with a cable anchored to shore. The crew momentarily docked to shore, cut the cable, returned to the AR location and retrieved the mooring and receiver. The Vemco representative is currently downloading data to a thumb drive and checking battery/memory status.

Jonni

(b) (6)

Photo 1: cable anchored to shore A27



Photo 2: preparing to download data from receiver



Get [Outlook for Android](#)